


## KN 95 mask cover instructions



Trace the outline of a KN 95 mask on cardboard.

Along the curved edge (where the elastic loops are attached) add  $\frac{1}{4}$  inch to make sure the cloth cover is large enough to completely cover the KN 95 mask. This is the stitching line. Mark the locations where the elastic is inserted on the curved edge. Mark the top corner where the KN 95 mask has its metal strip. (The lines and angles on the front of the mask are not symmetrical.)

Cut out the template on the stitching line.

Trace twice (once in reverse) around the template on the back of both outer fabric and lining fabric. Using a light print fabric for the lining results in a reversible cover.

Cut out all 4 pieces of fabric  $\frac{1}{4}$  inch beyond the cutting line.

Pin 2 outside fabrics right sides together and stitch on the 3 angled lines. This is the center seam of the cover.

Pin and stitch the lining fabric center seam as well.

Press the seam allowance on the outer fabric to one side and the lining fabric to the other side to reduce bulk.

Pin the lining and outer fabrics right sides together and stitch along top and bottom, leaving an opening between the elastic insertion points on both sides.

Turn cover right side out through one of the side openings and press the edge.

Cut a piece of fabric about 1.5" by 3" and stitch a narrow hem on all 4 sides.

Cut this rectangle in half resulting in 2 squares of fabric.

Insert the cut end of a square into each opening on the sides of mask and pin in place.

Top stitch all the way around the mask, starting at top center and securing the square tabs on the sides.

To wear the mask, fold the tabs to the inside of a KN 95 mask and secure tabs with paper clips. Remove cover after use to help KN 95 mask dry completely before next use.

